



P1010 100t/m

$\alpha = 75^\circ$, R= 0.8mm
 $\alpha = 88^\circ$, R= 0.8mm, 1.5mm, 3.0mm




P1010/105 100t/m

$\alpha = 75^\circ$, 88°
R= 0.8mm




P1012 60t/m

$\alpha = 30^\circ$, 35°
R= 1mm




P1012 / 200 50t/m

$\alpha = 30^\circ$
R= 0.8 mm




P1013 100t/m

$\alpha = 35^\circ$, R= 5mm
 $\alpha = 60^\circ$, R= 6mm
 $\alpha = 80^\circ$, R= 6mm




P1013 / 115 100t/m

$\alpha = 35^\circ$, R= 5mm
 $\alpha = 60^\circ$, R= 6mm




P1014 60t/m

$\alpha = 75^\circ$, A= 9mm, R= 0.8mm, *30 t/m
 $\alpha = 88^\circ$, A= 6mm, R= 0.2mm, 0.8mm
 $\alpha = 88^\circ$, A= 9mm, R= 0.2mm, 0.8mm




P1015 50t/m

$\alpha = 85^\circ$, R= 0.8mm,




P1016 20t/m


$\alpha = 88^\circ$, 90°
F= 0.6mm




P1017 100t/m
 $\alpha = 26^\circ$
 $R = 0.8\text{mm}$




P1017W 40t/m
 $\alpha = 30^\circ$
 $R = 0.8\text{mm}$




P1018 60t/m
 $\alpha = 60^\circ$
 $R = 0.8\text{mm}$




P1019 60t/m
 $\alpha = 88^\circ$
 $R = 0.8\text{mm}$




P1020 50t/m
 $\alpha = 75^\circ, R = 0.8\text{mm}$
 $\alpha = 85^\circ, R = 0.8\text{mm}$




P1021 100t/m
 $\alpha = 30^\circ, R = 0.8\text{mm}, 3\text{mm}$




P1022 50t/m
 $\alpha = 75^\circ, R = 0.8\text{mm}$




P1022/115 45t/m
 $\alpha = 30^\circ, R = 0.8\text{mm}$




P1024 30t/m
 $\alpha = 85^\circ, R = 0.2\text{mm}$




P1025 40t/m
 $\alpha = 88^\circ, 90^\circ$
 $R = 0.2\text{mm}$




P1026 30t/m
 $\alpha = 88^\circ, 90^\circ$
 $R = 0.2\text{mm}$




P1027 60t/m
 $\alpha = 30^\circ$
 $R = 0.8\text{mm}$




P1028 80t/m
 $\alpha = 85^\circ$
 $R = 0.8\text{mm}$




P1029 60t/m
 $\alpha = 85^\circ$
 $R = 5\text{mm}, 6.5\text{mm}$



P1030 60t/m
 $\alpha = 85^\circ$
 $R = 0.8\text{mm}$




P1031 60t/m
 $\alpha = 60^\circ$
 $R = 0.8\text{mm}$




P1032 45t/m

$\alpha = 88^\circ$
R= 0.8mm




P1033 70t/m

$\alpha = 28^\circ$
R= 0.6mm,
A=8mm, 10mm, 12mm




P1034 35t/m

$\alpha = 60^\circ$
R= 0.8mm




P1035 35t/m

$\alpha = 60^\circ$
R= 0.8mm




P1036 30-57t/m

$\alpha = 88^\circ$
R= 0.8mm, 3mm




P1037 70t/m

$\alpha = 85^\circ$
R= 0.8mm




P1038 43-80t/m


$\alpha = 85^\circ$
R= 0.8mm, 2mm




D4003




D4004




D4005




D4005/115




D4002




**D4009
R7-R12**




**D4009
R12.5-R50**




P/D3006




P/D3007




**Avrupa Bağlantı (European Standard)
Standart Parça Özellikleri**




D2008 100t/m




D2009 80t/m



D2009/85 80t/m




D2009/60 60t/m




D2011/30/18 80t/m

$\alpha = 30^\circ$
V= 18mm




D2011/30/25 50t/m

$\alpha = 30^\circ$
V= 25mm




D2011/45/32 90t/m

$\alpha = 45^\circ$
V = 32mm




D2011/85/32 90t/m

$\alpha = 85^\circ$
V = 32mm




D2011/45/40 100t/m

$\alpha = 45^\circ$
V = 40mm




D2011/85/40 100t/m

$\alpha = 85^\circ$
V = 40mm




D2011/60/50 100t/m

$\alpha = 60^\circ$
V = 50mm




D2011/85/50 100t/m

$\alpha = 85^\circ$
V = 50mm




D2011/60/63 100t/m

$\alpha = 60^\circ$
V= 63mm




D2011/85/63 100t/m

$\alpha = 85^\circ$
V= 63mm




D2011/85/80 100t/m

$\alpha = 85^\circ$
V= 80mm




D2011/85/100 100t/m

$\alpha = 85^\circ$
V= 100mm




D2011/80/125 70t/m

$\alpha = 80^\circ$
V= 125 mm



D2030



D2030/6 30t/m

$\alpha = 30^\circ$
V= 6mm, B=14 mm
R1= 0,6mm, R2= 0,6mm
H= 80mm, 120mm

D2030/8 30t/m

$\alpha = 30^\circ$
V= 8mm, B=18mm
R1= 1mm, R2= 1mm
H= 80mm, 120mm

D2030/10 35t/m

$\alpha = 30^\circ$
V= 10mm, B= 24mm
R1= 1mm, R2= 1mm
H= 80mm, 120mm

D2030/12 35t/m

$\alpha = 30^\circ$
V= 12mm, B= 24mm
R1= 1mm, R2= 1mm
H= 80mm, 120mm


D2030/16 35t/m

$\alpha = 30^\circ$
V= 16mm, B= 30mm
R1= 2mm, R2= 2mm
H= 80mm, 120mm

D2030/20 35t/m

$\alpha = 30^\circ$
V= 20mm, B= 35mm
R1= 2,5mm, R2= 3mm
H= 80mm, 120mm

D2045




D2045/10 50t/m

$\alpha = 45^\circ$
V= 10mm, B=18mm
R1= 2mm, R2= 1mm
H= 80mm, 120mm

D2045/12 50t/m

$\alpha = 45^\circ$
V= 12mm, B= 24mm
R1= 2,5mm, R2= 1mm
H= 80mm, 120mm

D2060



D2060/8 60t/m

$\alpha = 60^\circ$
V= 8mm, B=14mm
R1= 1,5mm, R2= 0,8mm
H= 80mm, 120mm

D2060/10 60t/m

$\alpha = 60^\circ$
V= 10mm, B=16mm
R1= 2mm, R2= 1mm
H= 80mm, 120mm

D2060/12 60t/m

$\alpha = 60^\circ$
V= 12mm, B= 18mm
R1= 2,5mm, R2= 1mm
H= 80mm, 120mm

D2060/16 60t/m


$\alpha = 60^\circ$
V= 16mm, B= 24mm
R1= 1,5mm, R2= 1,5mm
H= 80mm, 120mm

D2060/20 60t/m

$\alpha = 60^\circ$
V= 20mm, B= 30mm
R1= 2mm, R2= 2mm
H= 80mm, 120mm

D2060/25 60t/m

$\alpha = 60^\circ$
V= 25mm, B= 40mm
R1= 3mm, R2= 3mm
H= 80mm, 120mm

D2085**D2085/6 100t/m** $\alpha = 85^\circ$

V= 6mm, B=12mm

R1= 1.5mm, R2= 0.5mm

H= 80mm, 120mm

D2085/8 100t/m $\alpha = 85^\circ$

V= 8mm, B=14mm

R1= 1mm, R2= 0.5mm

H= 80mm, 120mm

D2085/10 100t/m $\alpha = 85^\circ$

V= 10mm, B= 16mm

R1= 1mm, R2=1mm

H= 80mm, 120mm

D2085/12 100t/m $\alpha = 85^\circ$

V= 12mm, B=18mm

R1= 2.5mm, R2= 1mm

H= 80mm, 120mm

D2085/16 100t/m $\alpha = 85^\circ$

V= 16mm, B= 22mm

R1= 2.5mm, R2= 1mm

H= 80mm, 120mm

D2085/20 100t/m $\alpha = 85^\circ$

V= 20mm, B= 30mm

R1= 3mm, R2= 3mm

H= 80mm, 120mm

D2085/25 100t/m $\alpha = 85^\circ$



V= 25mm, B=40mm

R1= 3mm, R2= 3mm

H= 80mm, 120mm


D3000 100t/m

A= 8mm, 10mm, 12mm




D3001/30/6 60t/m

$\alpha = 30^\circ$
V= 6mm




D3001/30/8 100t/m

$\alpha = 30^\circ$
V= 8mm




D3001/26/10 100t/m

$\alpha = 26^\circ$
V= 10mm




D3001/26/12 100t/m


$\alpha = 26^\circ$
V= 12mm




D4014 100t/m



D4015 100t/m




D4016 100t/m




INT 1

L= 150mm
H= 100mm, 150mm




INT 2

L= 150mm
H= 120mm




INT 3

L= 150mm
H= 100mm




INT 4

L= 150mm
H= 100mm




INT 5

L= 150mm
H= 100mm



INT/A

L= 150mm
H= 50mm



INT/S

L= 150mm
H= 58mm

